

Wire resistors SR Passives

SR[—]**PASSIVES**

| | |
|---------------------------------|-------------|
| Resistor type | wire-wound |
| Tolerance | ±5% |
| Temp. coeff. | 200 ppm/°C |
| Number of mounting holes | 2 |
| Leads | solder lugs |



| Symbol | Resistance [Ω] | Power [W] | Body dim. [mm] | Mount. holes pitch [mm] |
|-----------|----------------|-----------|----------------|-------------------------|
| R50W-1R | 1 | 50 | Ø25 x 120 | 142 |
| R50W-2R2 | 2.2 | 50 | Ø25 x 120 | 142 |
| R50W-4R7 | 4.7 | 50 | Ø25 x 120 | 142 |
| R50W-10R | 10 | 50 | Ø25 x 120 | 142 |
| R50W-22R | 22 | 50 | Ø25 x 120 | 142 |
| R50W-47R | 47 | 50 | Ø25 x 120 | 142 |
| R50W-100R | 100 | 50 | Ø25 x 120 | 142 |
| R50W-220R | 220 | 50 | Ø25 x 120 | 142 |
| R50W-470R | 470 | 50 | Ø25 x 120 | 142 |
| R50W-1K | 1 k | 50 | Ø25 x 120 | 142 |